

Motor Mount

drive unit, the side motor mount was upgraded.

Quantity

BLY (1028034 1

ply - Rear - LH

rear halfshaft assembly.

Quantity

PERFORMANCE 1

0.00

20296-00-B) 1

1020297-00- 1

ply - Rear - RH

rear halfshaft assembly.

Quantity

PERFORMANCE 1

20296-00-B) 1

1020297-00- 1

rear hub. Vehicle operating as designed.

Quantity

ASSY 1

)

rear hub. Vehicle operating as designed.

Quantity

ASSY 1

)

Concern: Customer: Vehicle will not shift into gear. Drive unit must be replaced.

Corrections: Instrument Panel General Diagnosis

Rear large drive unit needs, halfshaft assemblies and hubs need to be replaced.

Corrections: Drive Unit - Rear - Large

Replace rear Drive Unit and performed test drive. Vehicle operating as designed.

Parts Replaced or Added

Part	Quantity
ASY,P- TRAIN,RMN,MDLS,BASE,CMC,HS,FA2+ (1025276-00-Q)	1
G-48 COOLANT (1029320-00-A)	1
212-B ATF (1031106-00-A)	3