Job Number	Description Of Work	Amount (USD)
1	**Concern:** Infotainment: If like to schedule the MCU1 to MCU2 upgrade if it's available.	

Correction: NO LABOR PERFORMED

	Price	Adjustment	Subtotal
	0.00	0.00	0.00

Parts Replaced or Added

Part	Quantity	Unit Price	Price	Adjustment	Subtotal
MCU Upgrade(1582613-00-A)	1.0	2,500.00	2,500.00	0.00	2,500.00
				Parts Subtotal	2,500.00

Pay Type: Customer Pay — **2,500.00**

Total Parts Amount 2,500.00

4	**Concern:** Full Self-Driving Computer Retrofit (Model S and Model X Group 1)	

Correction: Full Self-Driving Computer Retrofit, Model X

Parts Replaced or Added

Part	Quantity
ASSY,AUTOPILOT.ECU,3.0-MSX-FUSED(1655000-70-F)	1.0

Pay Type: Customer Pre-Pay — **0.00**

5	**Concern:** Reroute Main Front Body Harness	

Correction: Reroute Main Front Body Harness

Pay Type: Basic Vehicle Limited Warranty — **0.00**

6	**Concern:** Additional items for infotainment upgrade.	

Correction: Infotainment Upgrade From Tegra MCU and Autopilot 2.5 To Intel MCU And Autopilot 3.0 (Model X)

Parts Replaced or Added

Part	Quantity
MCU INTEL HW3 UPGRADE-For TegraAP2.5- NA (9874561-00-A)	1.0

Pay Type: Customer Pre-Pay — **0.00**