



**TESLA MOTORS
AUSTRALIA, PTY LTD**
1062 Ann Street
Fortitude Valley, QLD 4006
Ph: +61284249500
Fax:
ABN 68 142 889 816

Tax Invoice

SERVICE DEPARTMENT HOURS

Mon-Fri: By Appointment Only

Please contact +61 459 890 410

Arctick Licence Number:
AU29329

Licence number: MVRL50462

Invoice Date	Reference Number
23-Apr-2018	RONs417001262
Date/Time Received	Date/Time Promised
23-Apr-2018 08:03	23-Apr-2018 10:30
Odometer In	Odometer Out
77743 KM	77747 KM
Ready Date	
23-Apr-2018 13:28	
Service Advisor	
Brendan van de Donk	

Bill To	Mobile Phone	Additional Phone		Vehicle Identification Number
Ray Newman 4019/4 Parkland Boulevard, Brisbane, QLD 4000 ray@woopwoop.com	+61418400700			5YJSB7H12FFP59526
	Year	Model	License Plate	Color
	2015	Model S		Pearl White Exterior Color

Job Number	Description Of Work	Amount (AUD)																					
1	Concern: Customer: Install relay box to increase single phase charging to 32amp.																						
	Corrections: Install Relay Box to Enable 32 A Single Phase Charging Installed relay box to increase single phase charging to 32amp.																						
	<table><tr><th>Part</th><th>Quantity</th><th>Unit Price</th><th></th></tr><tr><td>HIGH VOLTAGE JUNCTION BOX TO RELAY BOX SLAVE HARNESS ASSEMBLY (1046995-00-C)</td><td>1.00</td><td>0.00</td><td>0.00</td></tr><tr><td>DUAL LOCK 25MM X 20MM (1008246-00-B)</td><td>1.00</td><td>0.00</td><td>0.00</td></tr><tr><td>BOLT,M6,12.7MM,TF (1060341-00-A)</td><td>1.00</td><td>0.00</td><td>0.00</td></tr><tr><td>Total Parts</td><td></td><td></td><td>0.00</td></tr></table>	Part	Quantity	Unit Price		HIGH VOLTAGE JUNCTION BOX TO RELAY BOX SLAVE HARNESS ASSEMBLY (1046995-00-C)	1.00	0.00	0.00	DUAL LOCK 25MM X 20MM (1008246-00-B)	1.00	0.00	0.00	BOLT,M6,12.7MM,TF (1060341-00-A)	1.00	0.00	0.00	Total Parts			0.00		
	Part	Quantity	Unit Price																				
	HIGH VOLTAGE JUNCTION BOX TO RELAY BOX SLAVE HARNESS ASSEMBLY (1046995-00-C)	1.00	0.00	0.00																			
	DUAL LOCK 25MM X 20MM (1008246-00-B)	1.00	0.00	0.00																			
	BOLT,M6,12.7MM,TF (1060341-00-A)	1.00	0.00	0.00																			
	Total Parts			0.00																			
	<table><tr><td>Total Job Parts</td><td></td><td></td><td>0.00</td></tr></table>	Total Job Parts			0.00																		
	Total Job Parts			0.00																			
<table><tr><td>Total Labor & Miscellaneous Items</td><td></td><td></td><td>0.00</td></tr></table>	Total Labor & Miscellaneous Items			0.00																			
Total Labor & Miscellaneous Items			0.00																				
Pay Type: Goodwill - Service																							

	Concern: Perform courtesy inspection.		
--	---------------------------------------	--	--

2

Corrections: Courtesy Inspection

- Checked for active faults: No active faults found 4.23.2018).
- Checked firmware version: Updated to latest version 14.2
- Topped off washer fluid.
- Vehicle charged normally.
- Adjusted tire pressure to: 45 PSI front, 45 PSI rear.
- Measured tire tread depth at:
(Outer) (Center) (Inner)
LF: 7.5 7.8 7.8
RF: 7.8 7.8 7.6
LR: 6.5 6.5 6.8
RR: 6.5 6.6 6.7

Carried out car wash and vacuum

Total Job Parts			0.00
-----------------	--	--	------

Total Labor & Miscellaneous Items			0.00
-----------------------------------	--	--	------

Pay Type: Goodwill - Service

Service Centre hourly rate: AUD 172.73

Notes:

Total Labor & Miscellaneous Items	AUD	0.00
Total Parts	AUD	0.00
Shipping	AUD	0.00
Discount	AUD	0.00
Subtotal	AUD	0.00
GST	AUD	0.00
Referral Credit	AUD	0.00
TOTAL AMOUNT	AUD	0.00


You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla, its affiliates and their respective employees may access and operate your vehicle or transport your vehicle to another Tesla service location for the sole purpose of repairs, testing and/or inspection of repairs; Tesla, its affiliates and their respective employees may access, download and use the information stored on your vehicle's data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanic's lien is hereby acknowledged on your vehicle to secure the amount of repairs and storage; the owner's insurance provides exclusive coverage for the vehicle while it is in Tesla's possession; and you may be charged storage fees from the fourth day after you are notified that repairs on your vehicle are complete. Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New Vehicle Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. You authorize the repair work, including parts, materials and labor, on your vehicle to be done as set forth in this service agreement document. Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods.

Signature:

Date:

The warranty period will be extended for the number of whole days that the product has been out of the buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer, or if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts, the defect has not been fixed, the buyer may return this product for a replacement or a refund subject, in either case, to deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the buyer has under other laws.

Repairs



Internal Use Only

Payment



Internal Use Only