

Correction: Courtesy Inspection

4

Pay Type: Goodwill - Service

0.00

Concern: Addition items for Infotainment Upgrade.

-Additional items for Infotainment Upgrade.

Correction: Infotainment Upgrade From Tegra MCU To Intel MCU And Retrofit MCU Jumper Harness (Model S)

Parts Replaced or Added

Part	Quantity
MCU INTEL UPGRADE-For TegraAP1.0-NA(9874564-00-B)	1.0
INSTRUMENT CLUSTER(1447934-00-D)	1.0
Rear View Camera HSD Jumper(1127304-00-B)	1.0
ANTENNA , BLUETOOTH(1052393-00-B)	1.0

5

Pay Type: Customer Pre-Pay

0.00

Concern: Perform Infotainment Upgrade.

- Performed the Infotainment Media Control Unit Retrofit Upgrade per customer's request.
- Performed a Vehicle Firmware Update - Success.
- Performed a Validation Road Test - Passed.
- Verified proper fitment and operation - Good.
- Media Control Unit 2 is operating as per intended at this time.

Correction: NO LABOR PERFORMED

Price	Adjustment	Subtotal
0.00	0.00	0.00

Parts Replaced or Added

Part	Quantity	Unit Price	Price	Adjustment	Subtotal
Info Upgrad wit Replacement Touchscren(1582613-00-A)	1.0	2,500.00	2,500.00	(600.00)	1,900.00

6

Parts Subtotal 1,900.00

Pay Type: Customer Pay

1,900.00

Total Parts Amount 1,900.00