

CL


[SF bay area](#) > [north bay](#) > [for sale](#) >[cars & trucks - by owner](#)

Posted 4 days ago on: 2019-12-30 17:54

Contact Information:

## Tesla Roaster 2008 - Needs Battery - \$25000 (mill valley)

image 1 of 8

**2008 Tesla Roadster**drive: **rwd**fuel: **electric**odometer: **37017**paint color: **grey**title status: **clean**transmission: **automatic**type: **convertible**

Car is in Mill Valley, CA in my garage. 2008 Tesla Roadster. Bricked (bricked by a Dealer) Needs battery. Photo cutoff should save "needs replacement" for three of the sheets and one says "may need replacement." This one will most definitely be a piece of automotive history, especially if Tesla survives as a company. Car is in great condition cosmetically and mechanically, version 1.5 roadster with 37,017 miles. It does however does need a new ESS (battery pack) Attached in photos is a quote from Scottsdale, AZ Tesla Service center to complete, because it was there last month, and now back in California. Similar quote attached to photos. These batteries last a certain number of years (TBD), so a new battery

QR Code Link to This Post


would be a huge plus. Clean title. Plan was to hold on for 5-10 years for when they become very collectible and battery solutions are more affordable, or buy a new battery pack right away, or use one of the current alternate solutions, but need to make space for another rare car that is on the way... or find storage. This is my third Roadster.

2,450 roadsters were made and shipped to 30 countries. Fewer are remaining. The first year models are most collectible, but the later models had a few more convenience and comfort features. The production numbers are not as low as the 1,580 of a potentially million dollar 1972 911 RS, but 2,450 is also very low. The RS appreciated from the beginning, but did not go crazy until many years later. The computer can boot up on the car by applying 12 volts to the posts in front of the right rear wheel.



Thank you for looking!

brickedteslaroadster gmaol



Done 1 of 2

1 of 2 2008 Tesla Roadster (1) 12/20/07 12/20/07 12/20/07 12/20/07

Service Estimate

Customer: [Name] Address: [Address] City: [City] State: [State] Zip: [Zip]

Service Advisor: [Name] Technician: [Name]

Vehicle Make: [Make] Vehicle Model: [Model] Vehicle Year: [Year]

Estimate # [Number] Date: [Date] Time: [Time] Status: [Status]

Item Number	Description of Work	Amount
1	Customer: [Name] Service: [Service] Parts: [Parts] Labor: [Labor] Total: [Total]	\$1,200.00
2	Customer: [Name] Service: [Service] Parts: [Parts] Labor: [Labor] Total: [Total]	\$1,200.00

Service Center Ready: [Status] (12/20/07) (12/20/07) (12/20/07) (12/20/07)

Total Labor & Materials: \$1,200.00  
 Taxes: \$1,200.00  
 Total: \$2,400.00  
 Payment: \$1,200.00  
 Balance: \$1,200.00  
 Sales Tax: \$1,200.00  
 Total Due: \$2,400.00

Notes: [Notes]

Corrections: Battery Assembly - Roadster 1.5 (Remove & Replace)				
<b>Parts Replaced or Added</b>				
<b>Part</b>	<b>Quantity</b>	<b>Unit Price</b>		
ASY, ESS - Remanufactured (6003973)	1	14,500.00	14,500.00	15,213.00
	<b>Total Parts</b>		<b>14,500.00</b>	
<b>Total Job Parts: 14,500.00</b>				
<b>Total Labor &amp; Miscellaneous Items: 713.00</b>				
Pay Type: Customer Pay				
Concern: Perform courtesy inspection.				
Corrections: Courtesy Inspection				
Pay Type: Goodwill - Service				
				0.00



Another quote from Tesla from October

Here is the actual quote

Service/Labor	FRT Hours	FRT Price
Battery Assembly - Roadster 1.5 (Remove & Replace)	4.6	195.00
<b>Subtotal Labor Price: (USD)</b>		<b>897.00</b>
Parts:		Price
6003973 - ASY, ESS - Remanufactured		14,500.00
1015625-00-A - ANTI-FREEZE, SIERRA		28.00
1015625-00-A - ANTI-FREEZE, SIERRA		28.00
<b>Subtotal Parts Price: (USD)</b>		<b>14,556.00</b>
Subtotal Services and Parts: (USD)		15,453.00
Discount: (USD)		0.00
Shipping: (USD)		0.00
Estimated Tax: (USD)		1,200.87
Total Amount: (USD)		16,653.87

Note: This is a quote on list price, actual prices may vary at the time