



Tesla, Inc
3020 Pullman Street
Costa Mesa, CA, US 92626
Ph.: 714-641-3949

Service Estimate

SERVICE DEPARTMENT HOURS
Mon-Fri 8:00 a.m. - 5:00 p.m
Saturday-Sunday Sat: 9:00 a.m. - 5:00 p.m.

B.A.R.# ARD00277705
E.P.A.ID# CAC002807355

| Invoice date | Invoice number |
|----------------------|----------------------|
| 06-Jan-2023 | |
| Due Date | |
| 06-Jan-2023 | |
| Date/Time Received | Date/Time Promised |
| 05-Jan-2023 07:22:19 | 05-Jan-2023 18:00:09 |
| Odometer In | Odometer Out |
| 9707 Miles | Miles |
| Ready Date | |
| | |
| Service Advisor | |
| | |

| Bill To | Mobile Phone | Additional Phone | Vehicle Identification Number |
|---------|--------------|----------------------|-------------------------------|
| | | | 5 |
| Year | Model | License Plate Number | Colour |
| 2022 | MODEL S | | Midnight Silver Metallic |

| Job Number | Description Of Work | Amount (USD) | |
|------------|---|--------------|-------------------------|
| 1 | Concern: Check tire pressure and condition | | |
| | Correction: Check and Adjust Tire Pressure | | |
| | Correction: Windshield Washer Fluid - Top Off | | |
| | Correction: Checked Tire Tread Depth | | |
| | Pay Type: Goodwill - Service | 0.00 | |
| 2 | Concern: SI-22-21-002 | | |
| | Correction: Replace Car Computer, 2021+ Model S; Ethernet Diagnostics Retrofit Performed | | |
| | Parts Replaced or Added | | |
| | Part Ethernet Diagnostic - RJ45 Module(1681904-00-A) | | Quantity 1.00 |
| | TLA,AP-T,CONN-Q,MCU- Z,MSX FUSED(1637790-S0-F) | | 1.00 |
| | MCU,RJ45,JUMPER(1783315- 00-A) | | 1.00 |
| | Pay Type: Basic Vehicle Limited Warranty | 0.00 | |
| 3 | Concern: LEAD QC Test for Steam Functionality | 0.00 | |