



Tesla, Inc
 3020 Pullman Street
 Costa Mesa, CA, US 92626
 Ph.: 714-641-3949

Invoice

SERVICE DEPARTMENT HOURS
 Mon-Fri 8:00 a.m. - 5:00 p.m
 Saturday-Sunday Sat: 9:00 a.m. - 5:00 p.m.

B.A.R.# ARD00277705
 E.P.A.ID# CAC002807355

Invoice date	Invoice number
04-Jan-2023	
Due Date	
04-Jan-2023	
Date/Time Received	Date/Time Promised
03-Jan-2023 08:55:51	03-Jan-2023 18:30:59
Odometer In	Odometer Out
9654 Miles	9664 Miles
Ready Date	
03-Jan-2023 17:17:29	
Service Advisor	

Paid

Bill To

Mobile Phone	Additional Phone	Vehicle Identification Number	
Year	Model	License Plate Number	Colour
2022	MODEL S		Midnight Silver Metallic

Job Number	Description Of Work	Amount (USD)																				
1	<p>Concern: Customer states: Other · Upgrades & Accessories - Need steam games hardware upgrade since I have 8 gb of ram and I need 16 gb of ram</p> <p>technician Replaced Car Computer.</p> <p>Correction: Car Computer (Remove & Replace)</p> <table border="0" style="width: 100%;"> <tr> <td style="width: 50%;"></td> <td style="text-align: right;">Price</td> <td style="text-align: right;">Adjustment</td> <td style="text-align: right;">Subtotal</td> </tr> <tr> <td></td> <td style="text-align: right;">204.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">204.00</td> </tr> </table> <p>Parts Replaced or Added</p> <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Part</td> <td style="width: 10%;">Quantity</td> <td style="width: 15%;">Unit Price</td> <td style="width: 15%;">Price</td> <td style="width: 15%;">Adjustment</td> <td style="width: 15%;">Subtotal</td> </tr> <tr> <td>TLA,AP-T,CONN-Q,MCU-Z,MSX FUSED(1637790-S0-D)</td> <td style="text-align: center;">1.00</td> <td style="text-align: right;">1,825.00</td> <td style="text-align: right;">1,825.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">1,825.00</td> </tr> </table> <p style="text-align: right;">Parts Subtotal 1,825.00</p> <p style="text-align: right;">Pay Type: Customer Pay</p> <p>Total Parts Amount 1,825.00 Total Labor Amount 204.00</p>		Price	Adjustment	Subtotal		204.00	0.00	204.00	Part	Quantity	Unit Price	Price	Adjustment	Subtotal	TLA,AP-T,CONN-Q,MCU-Z,MSX FUSED(1637790-S0-D)	1.00	1,825.00	1,825.00	0.00	1,825.00	2,029.00
	Price	Adjustment	Subtotal																			
	204.00	0.00	204.00																			
Part	Quantity	Unit Price	Price	Adjustment	Subtotal																	
TLA,AP-T,CONN-Q,MCU-Z,MSX FUSED(1637790-S0-D)	1.00	1,825.00	1,825.00	0.00	1,825.00																	
2	<p>Concern: Check tire pressure and condition</p> <p>Inspected tire tread depth. Tread Depth Measure Type mm Tread depth - Record the lowest measurement across all groves Front Driver: 5 Front Passenger: 5 Back Driver: 5 Back Passenger: 5 Tire replacement recommended No Tire rotation recommended</p>	0.00																				

	No	
	Correction: Automated Tire Pressure Check	
	Correction: Checked Tire Tread Depth	
		Pay Type: Goodwill - Service
3	Concern: Automated tire pressure check; tire pressure adjustment recommended Set tire pressure to target values shown on the Tire and Loading Information label. Correction: Set Tire Pressure	Pay Type: Goodwill - Service 0.00

Service Center hourly rate: USD 240

All parts are new unless otherwise specified.

You agree that: Tesla is not responsible for any personal items left in your vehicle; Tesla and its employees may access and operate your vehicle including on streets, highways, or public roadways for the sole purpose of testing and/or inspection of repairs; Tesla may update your vehicle's software in the course of a repair or as part of the standard vehicle maintenance process per your owner's manual and New Vehicle Limited Warranty; Tesla and its employees may access, download and use the information stored on your vehicle's data recorder to service and diagnose issues with your vehicle, and Tesla may store and aggregate such data for its own purposes; an express mechanic's lien is hereby acknowledged on your vehicle to secure the amount of repairs, storage and other applicable fees; the vehicle owner's insurance provides exclusive coverage for the vehicle while it is in Tesla's possession; and you may be charged storage fees of \$35/day from the fourth working day after you are notified that repairs on your vehicle are complete and that the vehicle is ready for pick up.

Total Parts (USD)	1,825.00
Total Labor (USD)	204.00
Discount	0.00
Subtotal (USD)	2,029.00
Tax	141.44
Total Amount (USD)	2,170.44
Total Paid (USD)	2,170.44
Payment Due (USD)	0.00

Tesla disclaims all express or implied warranties with respect to any repairs or products used in repairs, except as may be set forth in your Tesla-issued New or Used Vehicle Limited Warranty, Tesla Parts, Body, and Paint Repair Limited Warranty or other extended service agreement. Tesla is not responsible for repairs not performed by, or components not installed by, Tesla. Any parts (including tires/wheels) removed or replaced by Tesla during vehicle service will become the property of Tesla. However, at the time you authorize repairs, you may request to receive (subject to any applicable core charge, which you agree to pay) or inspect replaced parts (excluding inflatable restraint system components), except body shop repair parts and parts required to be returned to the manufacturer or a third party under a warranty, trade-in or exchange agreement, which will only be presented to you for examination and not returned.

I authorize the repair work, including parts, materials and labor, on my vehicle to be done pursuant to the terms and conditions as set forth in this service agreement document.

Signature:

Date:

Warning: Motor vehicles contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.

FullName: