

2

Concern: During service visit technician noted that all 4 tires are down to the chords. Replacement required.

Corrections: Tires - Vehicle - Set

Mounted, balanced and installed replacement tire set. Road tested to verify proper tracking and balance.

Parts Replaced or Added

Part	Quantity	Unit Price	
265/35R22 102W S GOODYEAR EAGLE F1 3 TIRE (1027254-00-B)	2	200.00	400.00
285/35R22 106W S GOODYEAR EAGLE F1 3 TIRE (1027255-00-B)	2	200.00	400.00
Total Parts			800.00

Corrections: Four Wheel Alignment - Check and Adjust (with Air Suspension)

Performed four wheel alignment at no charge as this was not provided in original quote for tires.

Total Job Parts: 800.00

Total Labor & Miscellaneous Items: 125.00

Pay Type: Customer Pay

925.00

3

Concern: Customer states there is a creaking noise while driving in the front right suspension area.

Corrections: Air Spring Module - Front - RH

Found noise coming from the front right air strut. Replaced air strut and verified noise is no longer present.

Parts Replaced or Added

Part	Quantity	
AIR SPRING MODULE FR (1027361-25-E)	1	

Pay Type: Warranty

0.00

Service Center hourly rate: USD 150.00

All parts are new unless otherwise specified.

Notes:

Payment Terms:
 Due upon receipt. PLEASE QUOTE THE INVOICE NUMBER
 WITH YOUR PAYMENT

Total Labor & Miscellaneous Items	125.00
Total Parts	800.00
Shipping	0.00
Discount	0.00
Referral Credit	0.00
Subtotal	925.00
Sales Tax	69.38
TOTAL AMOUNT	994.38

Additional Amount	Revised Estimate	Job Number	Date & Time	Approved By (# If By Phone)