

Vin: Signature 122

Things that need to be fixed:

1. Replace Tesla Key Fob for Model X
 - a. Key Fob intermittently stops working and I then have to use the iphone application, please replace the key fob
2. Black marks on ceiling of car





3. Scratch on rear/trunk window



4. Rubber or glue, not sure what it is, on side of Fulcon door panel



5. The last time it rained, when I opened the fulcon wing doors, water seeped inside to the seats, I don't believe its properly sealed



6. There is a dent that is around the frame of the falcon wing door



7. Scratches inside car



8. The driver side fulcon wing door, has numerous issues, its scratched and doesn't close correctly many times







9. Since the driver side falcon wing door doesn't close correctly, the door and the sides are scratched up



10. Border Scratched



11. Dent along the door



12. Another dent



13. Chrome Scratches





14. Big dent on the frame of the driver side Falcon Wing Door



15. Rear roof, glass chip, very sharp to touch, again caused by Falcon Door

