

Methods for resetting various features in the Model X:

Center Display

Press and hold both scroll buttons for a few seconds. Center console display will turn black and reboot.

Instrument Cluster

Press and hold both of the steering wheel buttons *above* the scroll wheels. IC display will turn black and reboot.

Power Off/Reset

Under Settings, E-Brake and Power Off. Power vehicle off, then use the brake to restart.

Front Door Calibration

From inside the vehicle, do a scroll wheel (touchscreen) reset.

Open the door from inside (the manual handle will always release the door).

Manually push the door to the full open position, then slowly and deliberately push the door manually closed so that it will latch. Close it slow enough that it takes about 5 to 10 seconds. If the latch pulls the door in, all is working okay.

Front Door Windows Calibration

Method 1

With the door closed, roll the window all the way down with a "soft click" (not the full down click). Hold the window down for at least 5 seconds after it is fully closed.

Roll the window back up with a soft click (not full up) and hold the window all the way up for at least 5 seconds.

Method 2 (Newer)

Open door.

Roll window down.

Auto-roll window up (pull up fully on the switch and release so it rolls itself up without you holding the switch).

When window is about half way open, give it a firm smack downwards from above. This simulates something getting stuck in the window and it will roll down to prevent injury.

Repeat this process until the window will no longer auto roll up. This can take 10-15 repetitions.

Close and open the door to verify

Falcon Wing Door Calibration

Take the vehicle outdoors where there's nothing in range of the FWD (and probably no overhead cache - that is, the display allows you to fully open the doors on one touch.) Hold the physical door switch inside the vehicle until door is all the way open. Next, hold the physical door switch down until the door is all the way closed. The door should be recalibrated at this point.

Falcon Wing Door Complete Reset:

Remove access panel in funk area (no tool required)

Disconnect emergency services power loop located under the orange sticker that should be above your funk space.

Get a stubby 13mm socket and disconnect ground strap (black wire bolted to chassis under the area of the Emergency Services loop.) Wait 20 Seconds. Reconnect it.

Plug the loop back in.

Center screen will suggest you need to recalibrate the doors.

This reset is needed when no button pushes or holds work and the door is completely non-responsive.

Vehicle Stuck in Park

Have all passengers exit Model X for 2 minutes with doors closed. Re-enter vehicle. Use Power Off/Reset Technique above. Wait 2 minutes, start vehicle again.

Active Spoiler Stuck Down

Put vehicle in park. Go to Settings, Service & Reset, Spoiler and set it to Extended. This will raise the spoiler up. Perform center display reset technique from above. Spoiler will remain up and fully extend as part of reset.