

Options

Tesla Service Estimate

0

Page 2 of 4

Service Center hourly rate: USD 175.

Correction: Tires - Vehicle - Set				Price	Adjustment	Subtotal
Parts Replaced or Added				160.00	0.00	160.00
Part	Quantity	Unit Price	Price	Adjustment	Subtotal	
275/45R20 CCLXS TDV1027257-00-B)	2.0	295.00	590.00	0.00	590.00	
265/45R20 CCLXS TDV1027256-00-B)	2.0	310.00	620.00	0.00	620.00	
Parts Subtotal					1,210.00	
Pay Type: Customer Pay						1,370.00
Total Parts Amount					1,210.00	
Total Labor Amount					160.00	

Start