


Moving blanket recommended or at least knee pads if you are limber enough to do from your knees.



Bracket is solid, protective coating, is not visible behind plate and at just the correct angle.



We put a 3/4" wide self-sticking gasket material behind plate. However, self-sticking chair pads could work. There is plenty of clearance between bumper and plate, however if someone tapped you the plate would be damaged but not the bumper IMO.



THE LAW TORKLIFT MX FRONT PLATE LICENCE PLATE HOLDER

Reviewed time to read directions, set up suspension to VERY HIGH, place moving blanket on ground, start, look at directions again and install. Should be 20-25 minutes to install for most people including opening the box. The day before it arrived I got stopped by the State Patrol in Lynnwood just getting onto I-405 South. "Where is your front plate?" Trooper was very friendly and accepted my story of having one on order. However, I am now in their database (no warning or ticket). Key words were "Torklift" THE LAW ON ORDER".

. <http://torkliftcentral.com/rving-and-towing/echohitch/tesla/tesla-accessories/the-law-tesla-auto-pilot-compatible-x7340>

Part number: x7340

Sale Price: \$110.99

Regular Price: \$125.99