



Vehicle Database Query Results - Latest 10 Test

**NOTE:** Only data that has been reviewed and released from NHTSA/OCR's quality control process is available via this interface.

Your query results are listed below. To view additional, detailed information for the test(s) in which you are interested, click on the corresponding links provided in the TEST NO., Instrumentation, Vehicle and Barrier columns. Selecting the corresponding Vehicle link will allow you to view Occupant and Restraint information associated with the chosen test.

Test No.	Multimedia Files	Test Reference No.	Test Type	Contractor Study Title	Test Performer	Impact Angle (degrees)	Test Configuration	Offset Distance (mm)	Closing Speed (kph)	Instrumentation Information	Vehicle Information	Barrier Information
11844	<a href="#">Photos</a> <a href="#">Reports</a> <a href="#">Videos</a>		FMVSS 301 FUEL SYSTEM INTEGRITY	FMVSS 301 TEST REPORTS/PHOTOS/VIDEO	CALSPAN	180	IMPACTOR INTO VEHICLE			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
11845	<a href="#">Photos</a> <a href="#">Reports</a> <a href="#">Videos</a>		FMVSS 301 FUEL SYSTEM INTEGRITY	FMVSS 301 TEST REPORTS/PHOTOS/VIDEO	KARCO ENGINEERING	180	IMPACTOR INTO VEHICLE			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
11846	<a href="#">Photos</a> <a href="#">Reports</a> <a href="#">Videos</a>	S18123	FMVSS 301 FUEL SYSTEM INTEGRITY	Simulation Test	MGA RESEARCH	80	SLED WITHOUT VEHICLE BODY		20	<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
11847	<a href="#">Photos</a> <a href="#">Reports</a> <a href="#">Videos</a>	S18124	FMVSS 301 FUEL SYSTEM INTEGRITY	Simulation Test	MGA RESEARCH	80	SLED WITHOUT VEHICLE BODY		20	<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
11875	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - BSI_2017_CAR_4_0024_02_01_Y	OTHER		BLIND SPOT INTERVENTION			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
12608	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - CIB_2017_CAR_7_0552_02_02_N	OTHER		CRASH IMMINENT BRAKING			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
12796	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - ISA_2019_CAR_1_0342_02_04_N	OTHER		INTERSECTION SAFETY ASSIST			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
12851	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - OTSA_2018_CAR_1_0307_02_02_N	OTHER		OPPOSING TRAFFIC SAFETY ASSIST			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
13302	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - TJA_2019_CAR_1_0231_04_01_N	OTHER		TRAFFIC JAM ASSIST			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>
13322	<a href="#">Photos</a> <a href="#">Reports</a>	NONE	VEHICLE OPERATIONAL SAFETY-CRITICAL SCENARIOS	COLLISION AVOIDANCE - TJA_2019_CAR_1_0284_03_01_N	OTHER		TRAFFIC JAM ASSIST			<a href="#">Instrumentation Information</a>	<a href="#">Vehicle Information</a>	<a href="#">Barrier Information</a>