

Glue or something around
driver side mirror



General modeling issues in several places



Passenger FWD not aligned
(higher than driver)



Seal issues



Seal issues



Small gap on drivers headlight



Tiny glue or something on
passenger side mirror




Molding issue



Passenger FWD molding



Slight crease on leather seat bottom
(only one)



Trunk picks up marks /
substance on open/close



Rear wheel gap #1



Wheel lining gap #2



Wheel gap #3



Passenger rear window alignment and molding



Driver side rear window alignment & molding



Driver inside interior door molding



Passenger FWD odd insert
of molding (foam?)



FWD molding issue inside




FWD inside arm (gap)



Internal FWD arm fitting gap



Rear View mirror odd glue/
oil streak won't clean



Driver side trunk liner wrinkle
different than passenger side



Rust or residue on third row
seating near trunk



Tiny question: Cable label on each side of rear seat is different (yellow vs. white)
Is this an issue?



More rust or substance on
exposed rear seat portions



Rust or substance on driver
side third row seat



Discoloration on interior paint on door (glue streaks or white streaks)



Wrinkle on third row seat
passenger side (not driver)



Middle seat wrinkle (not on other seats)



Middle seat wrinkle (not on other seats)

