



Tesla, Inc
3020 Pullman Street
Costa Mesa, CA, US 92626
Ph.: 714-641-3949

Invoice

SERVICE DEPARTMENT HOURS
Mon-Fri 8:00 a.m. - 5:00 p.m
Saturday-Sunday Sat: 9:00 a.m. - 5:00 p.m.

B.A.R.# ARD00277705
E.P.A.ID# CAC002807355

Paid

Invoice date	Invoice number
14-Jan-2023	
Due Date	
14-Jan-2023	
Date/Time Received	Date/Time Promised
13-Jan-2023 08:00:40	14-Jan-2023 17:00:51
Odometer In	Odometer Out
Ready Date	
14-Jan-2023 15:22:05	
Service Advisor	

Bill To	Mobile Phone	Additional Phone	Vehicle Identification Number
			5
Year	Model	License Plate Number	Colour
2022	MODEL S		Midnight Silver Metallic

Job Number	Description Of Work	Amount (USD)				
1	<p>Concern: Customer states: Other · Upgrades & Accessories - Just got steam deck retrofit. Pixel squares all over screen.</p> <p>Technician backed up profile removed and replaced car computer, performed firmware update restored profile and verified no alerts present. Technician functioned tested Steam deck and verified of proper operation.</p> <p>Correction: Car Computer (Remove & Replace)</p> <p>Parts Replaced or Added</p> <table><tr><th>Part</th><th>Quantity</th></tr><tr><td>MSX CAR COMPUTER - FUSED(1637790-S0-F)</td><td>1.00</td></tr></table> <p>Pay Type: Parts Warranty</p>	Part	Quantity	MSX CAR COMPUTER - FUSED(1637790-S0-F)	1.00	0.00
Part	Quantity					
MSX CAR COMPUTER - FUSED(1637790-S0-F)	1.00					
2	<p>Concern: Customer states: Other · Upgrades & Accessories - Just got steam deck retrofit. Pixel squares all over screen.</p> <p>Technician backed up profile removed and replaced car computer, performed firmware update restored profile and verified no alerts present. Technician functioned tested Steam deck and verified of proper operation.</p> <p>Correction: Remote Diagnosis</p> <p>Pay Type: Goodwill - Remote Support</p>	0.00				
3	<p>Concern: Check tire pressure and condition</p> <p>tire pressure Tread Depth Measure Type</p>	0.00				