

My Tesla P85 PED Inspection Report Overview		2017-10-27 21:38:24	
Submission Date			
Inspection Date	10-27-2017		
Service Center Location	NA-US-FL-West Palm Beach		
VIN	P05815		
Model Trim	Model S P85		
Odometer at Time of Inspection	46782		
Odometer Type	Miles		
Used Vehicle Qualification	Perform a Power Switch Resistance History Check Odometer Reading Verified Against Vehicle History Report All 3 VINs Verified No Current Mechanical Aftermarket Modifications No Current Frame Damage or Previous Frame Repair No Faults or Alerts		

My Tesla P85 PED Inspection Report Overview			
Two Functional Keys in Good Condition	Replace		
No Fluid Leaks	Pass		
Applicable Mobile Connectors Present, Inspected and Tested: 14-50 (1014324-00-E or higher) / J1772 (1005617-00-* Rev B or 1067348-00-A) / NEMA 5-15 110v adapter (grey housing)	Pass		
Supercharging	Pass		
High Power Wall Connector Charging	Pass		
Charge Port Door Hinge and Operation	Repair		

My Tesla P85 CPD Inspection Report Overview	
Drive Quality (Steering, Suspension and Vibration)	Pass
Cruise Control Function	Pass
Autopilot Function	Not Applicable
Air Suspension Function	Pass
Audio System Operation	Pass
All Music Inputs	Pass
Navigation	Pass
Rear Camera	Pass
Panoramic Roof Function	Pass
Air Conditioning Function	Pass
Heating System Function	Pass
My Tesla P85 CPD Inspection Report Overview	
Driver Seat Heater	Pass
Passenger Seat Heater	Pass
Trip Odometer Function	Pass
Windshield Wiper, Washer Jets, Function and Aiming	Pass
My Tesla P85 CPD Inspection Report Overview	
Park/Neutral/Drive/Reverse Shifting Function	Pass
Horn Operation	Pass
Turn Signal Stalk Function	Pass
Steering Scroll Wheels & Buttons	Pass
Steering Column Adjustment	Pass

My Tesla P85 CPD Inspection Report Overview

Left Hand Front Door Function	Repair
Left Hand Rear Door Function	Repair
Right Hand Rear Door Function	Repair
Right Hand Front Door Function	Pass
Steering Feel (Normal and Sport Modes)	Pass
Squeaks, Rattles, or Creaks	Pass
Wind Noise	Pass
Vibration or Abnormal Drive Unit Health or Noises	Pass
Ride Quality (Steering, Suspension and Vibration)	Pass

My Tesla P85 CPD Inspection Report Overview

Power Mirror Functionality	Repair
Hazard Lights Switch	Pass
Touchscreen Functionality	Repair
Maps For Correct Region	Pass
Mirror Adjustment	Pass
Mirror Fold	Repair
Left Hand Front Seat Track and Adjustment	Pass
Left Hand Front Seat Belt	Pass
Right Hand Front Seat Belt	Pass
Right Hand Front Seat Track and Adjustment	Pass

My Tesla P85 CPD Inspection Report Overview	
Bluetooth Call Functionality (Pair in Park)	Pass
Park Assist	Not Applicable
Check All Windows Using Individual Switches and Master Switch to Confirm Operation and No Abnormal Noises	Pass
Reset Touch Screen	Pass
Headlights Function	Pass
Fog Lights Function	Pass
Front Turn Signals Function	Pass
Rear Turn Signals Function	Pass
My Tesla P85 CPD Inspection Report Overview	
Tail Lights and Brake Lights Function	Pass
Frunk Manual Release (First and Second Latch)	Pass
Brake Fluid Level	Pass
Windshield Washer Fluid Level	Pass
Coolant Level	Pass
Frunk Carpet	Pass
Frunk Acoustic Absorber	Pass
First Responder Label (Right Hand Frunk Trim)	Pass

My Tesla P85 CPD Inspection Report Overview	
Tow Eye Present	Replace
4 of 7	
Front Panel	Pass
Interior Frunk Light	Pass
Emergency Release	Pass
Front Hood Hinges	Pass
Liftgate Emergency Release	Pass
Liftgate Trim	Pass
Parcel Shelf	Pass
Trunk Carpet	Pass
Trunk Trim	Pass
Vehicle Emissions Label (North America Only: Lower Liftgate Trim)	Pass
My Tesla P85 CPD Inspection Report Overview	
Matching Brand and Tire	Pass
Left Hand Front Lowest Tread (mm)	2
Left Hand Front Tire	Replace
Left Hand Rear Tread Lowest Tread (mm)	2
Left Hand Rear Tire	Replace
Right Hand Rear Lowest Tread (mm)	2
Right Hand Rear Tire	Replace
Right Hand Front Lowest Tread (mm)	2
Right Hand Front Tire	Replace
No Uneven Wear or Sidewall	Pass

My Tesla P85 GPO Inspection Report Overview		
Wheel Bearings	Pass	
Wheel Lip Appearance	Repair	
Wheel Center Caps	Pass	
Rotate as Necessary	Pass	
Correct Lug Nuts Fitted	Pass	
Left Hand Front Wheel Lug Torque (Nm)	175	
Left Hand Front Tire Pressure (PSI)	42	
Left Hand Rear Wheel Lug Torque (Nm)	175	
My Tesla P85 GPO Inspection Report Overview		
Front Rotors	Pass	
Front Brake Pads >6mm	Pass	
Rear Rotors	Pass	
Rear Brake Pads >6mm	Pass	
Park Brake Pads >3mm	Pass	
Brake Hose	Pass	
Lift Pad Inspection	Pass	
Vehicle Contains a Loaner HV Battery	No	
HV Battery Enclosure	Pass	
Front Shock Absorbers	Pass	
Front Wheel Arch Liners	Pass	

My Tesla P85 CPD Inspection Report Overview	
Motor Mounts	Pass
Drive Shafts	Replace
	RR outer boot torn
Check Torque on Front and Rear Suspension	Pass
Torque Check Date	10-27-2017
	Confirmed that Vehicle Specifications and Options Match the Options Displayed in Online Configuration Perform Vehicle Configuration Updates Run Toolbox Automatic Tests Install A/C compressor NVH Cover and Bracket (Vehicles Built Before July 2014) Replace HVAC drainage tube Verify Baolong TPMS Sensor Voltage (Vehicles Built Before September 17, 2014) Perform Annual Service if Needed and Perform a Four Wheel Alignment
Perform a Full Firmware	Pass